

Revision Date: 10.11.2022

BMW Group

Components

Regulation (EC) No. 648/2004, as amended

Windscreen washer without antifreeze

Product code : 83 12 5 A1A 174, 83 12 5 A1A 170

AQUA
SODIUM LAURETH SULFATE
ALCOHOL
PARFUM
SODIUM PYRITHIONE
CITRIC ACID
MEK
ISOPROPYL ALCOHOL
BENZISOTHIAZOLINONE
Cyclohexanol, 2-(1,1-dimethylethyl)-, 1-acetate, (1R,2R)-rel-
3-HEXENOL
(2E)-2-(Phenylmethylidene)octanal
DENATONIUM BENZOATE